
LOT 11
LOT 12
LOT 13
LOT 14
POD
EX.
EXISTING TO REMAIN (FIELD VERIFY)
LOT 15
LOT 16
LOT 17
LOT 18
LOT 19
LOT 20
LOT 21
SWI
29
EXISTING BUFFER TO REMAIN (FIELD VERIFY LOCATIONS)
LOT 22
LOT 23
LOT 24
NORTH LINE OF SE 1/4, SW 1/4, NE 1/4 OF SECTION 24
S89°43'05"E 620.41'
FOUND 5/8" IRON ROD (NO ID)
FOUND CUT NAIL & TAG (NO ID)
EXISTING SOD
ELECTRIC FENCE
CHAIN LINK FENCE with BARBED WIRE
NEW BAHIA SOD
125.3'
123.9'
303.3'
NO1°01'07"W 330.10'
CONCRETE
S89°43'05"E 25.00'
FOUND 5/8" IRON ROD (NO ID)
WEST LINE OF NE 1/4, SW 1/4, NE 1/4 OF SECTION 24
NO1°01'07"W 330.10'
SOLID YELLOW LINE
S88°31'14"W 150.00'
FOUND 5/8" IRON ROD (NO ID)
NORTH LINE OF ERIKA LAND PLAT (PB 150, PG 470
ERIKA LAND PLAT (PB 150, PG 470)
N01°01'07"W 184.40'(D)
PROPOSED OFFICE SPACE TO REPLACE EXISTING 5200 SF FFE = 13.13
EXISTING TO BE RELOCATED (FIELD VERIFY)
21" OAK
17" OAK
METAL FENCE
CONCRETE RETAINING WALL
BOLLARDS
SWITCH GEAR
ATT VAULTS
15' SIGHT VISIBILITY(TYP.)
RIGHT OF WAY
NORTH RIGHT OF WAY LINE PER O.R.B. 20933, PG 218
SIGN (JUNCTION 441)
MONUMENT & TAG SET MAG NAIL & DISC (LB 6018) ELEVATION = 11.54'
GRASS MEDIAN
2' CURB & GUTTER
CONCRETE MEDIAN
SW 58th AVENUE (2 LANE UNDISPUTED)
CENTERLINE OF 50' RIGHT OF WAY & EAST LINE OF SE1/4, SW1/4, NE1/4 OF SECTION 24
EXISTING POWER POLE
GUY WIRE
ANCHOR
CHAIN LINK FENCE with BARBED WIRE
FOUND CUT NAIL (NO ID) BROKEN
CHR 35
CHR 36
COC 6
CON 10
SAB 15
LAG 1
ILE 4
LIV 2
LYS 4
FIC 92
PTY 4
COR 9
TAX 6
SAB 3
CHR 84
COC 1
ILE 1
LIV 1 RELOCATED
LYS 2
FIC 56
PTY 2
FIC 36
SAB 3
CHR 48
LIV 2
LYS 2
YELLOW STRIPES
CHR 48
COR 9
SAB 3
CHR 18
LAG 3
LIV 1 RELOCATED
COC 1
CHR 20
SAB 6
LAG 1
CON 7
CHR 52
CON 9
CHR 92
CON 10
CHR 35
CHR 35
CHR 35